

Observation Number:	201605268
Originator:	
Date Created:	10-Aug-2016
Business Unit:	AS EAAA
Business Group:	Capital Projects EAAA
Project/Office:	EPC2 Antwerp
Service Line:	SERC
Site/Office Name:	EPC2 Antwerp - Site
Home or Work Related Observation?:	Work
Exact Location or Project of Act/Condition/Safe Behaviour:	Central Control House
Observation Type:	Safe Behaviour
Observer Name:	Cristian Loi
Observer Email Address:	TIOTIE.ExxonmobilAntwerp@fwceu.com
Stakeholder:	Contractor
Observation Date:	02-Aug-2016
Observation Time:	13:00
Observation Close Date:	12-Aug-2016
Name of Individual or Team:	TECHIMP
Details of safety observation:	TECHIMP crew were busy on the migration of emergency push buttons in the central control house from console 6 to console 5. The working area was particular because there inside it's required to pay particular attention to avoid to cause unit trip (the units are in service) and to don't disturb the operators that are working there or leave material on the floor causing trip hazards. In general they perform the activity with good housekeeping and good respect of the work of the other person present in the central control house.
Immediate action taken:	No actions but congratulations.
Supporting Information:	
Feedback required?:	No