

Observation Number:	201808469
Originator:	
Date Created:	25-Jun-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Sub Business Group:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	Woodland Rd Croesyceilog Cwmbran
Observation Type:	Unsafe Act
Observer Name:	John Ross
Observer Email Address:	trevor.clark@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	19-Jan-2018
Observation Time:	12:30
Observation Close Date:	27-Jun-2018
Details of safety observation:	ISL Intervention :Team member left a jack hammer on the side of a walk way which was noticed by T/L straight away
Immediate action taken:	T/L pulled team member to one side and explained the trip hazard for the safety of the public
Supporting Information:	
Feedback required?:	No