

<b>Observation Number:</b>	201900780
<b>Originator:</b>	
<b>Date Created:</b>	21-Jan-2019
<b>Business Unit:</b>	Projects
<b>Business Group:</b>	Process & Chemicals
<b>Project/Office:</b>	Shell Bukom EFA Projects
<b>Sub Business Group:</b>	APAC
<b>Site/Office Name:</b>	Shell Bukom
<b>Work Related or Non-Work Related Observation?:</b>	Work Related
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	TGU Pipe Rack Area
<b>Observation Type:</b>	Unsafe Condition
<b>Observer Name:</b>	Reddy Ashok Vellappa
<b>Observer Email Address:</b>	Ashok.reddy@woodplc.com
<b>Stakeholder:</b>	Wood
<b>Observation Date:</b>	10-Jan-2019
<b>Observation Time:</b>	01:45
<b>Observation Close Date:</b>	24-Jan-2019
<b>Observation Category:</b>	N/A N/A
<b>Details of safety observation:</b>	we take 4 in 1 gas monitor from Shell Design office but that day shortage of 4 in 1 gas monitor we cant get it so we check Wood Construction there also we can't get it and we get it from PU1 control room from Shell operation team
<b>Immediate action taken:</b>	So we inform Project and Request New 4 in 1 gas monitor
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No