

Observation Number:	201810256
Originator:	
Date Created:	18-Jul-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Service Line:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Home or Work Related Observation?:	Work
Exact Location or Project of Act/Condition/Safe Behaviour:	Dukestown Rd Tredegar
Observation Type:	Unsafe Condition
Observer Name:	Richard Date
Observer Email Address:	carl.jones@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	23-Mar-2018
Observation Time:	08:15
Observation Close Date:	18-Jul-2018
Details of safety observation:	Team came in this morning and all the signs and barriers were down - vandalism
Immediate action taken:	Team have made site safe and secure.
Supporting Information:	
Feedback required?:	No