

Observation Number:	201900370
Originator:	
Date Created:	10-Jan-2019
Business Unit:	E&I Solutions
Business Group:	Europe
Project/Office:	UK Built Environment
Service Line:	Remediation and Ground Engineering
Site/Office Name:	Shrewsbury (Built Environment)
Home or Work Related Observation?:	Work
Exact Location or Project of Act/Condition/Safe Behaviour:	Alderbury NGGT Site: Bottom of track off bridleway to site
Observation Type:	Unsafe Condition
Observer Name:	Lewis Miffling
Observer Email Address:	lewis.miffling@woodplc.com
Stakeholder:	3rd Party
Observation Date:	10-Jan-2019
Observation Time:	12:00
Observation Close Date:	11-Jan-2019
Observation Category:	Contractor Site safety Housekeeping
Details of safety observation:	Landowner complained about siting of skip for waste soil arisings which is 'scaring' horses on the bridleway
Immediate action taken:	Gap between skip and nearest obstruction measured to check clearance. Contacted contractor to arrange skip removal
Supporting Information:	
Feedback required?:	No