

<b>Observation Number:</b>	201809728
<b>Originator:</b>	
<b>Date Created:</b>	11-Jul-2018
<b>Business Unit:</b>	AS EAAA
<b>Business Group:</b>	Operations Services Europe & Africa
<b>Project/Office:</b>	Western Gas Alliance
<b>Sub Business Group:</b>	Transmission & Distribution
<b>Site/Office Name:</b>	Western Gas Alliance 1855005/6
<b>Work Related or Non-Work Related Observation?:</b>	Work Related
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	Barton Street, Tewkesbury
<b>Observation Type:</b>	Unsafe Act
<b>Observer Name:</b>	Mick Bryan
<b>Observer Email Address:</b>	carl.jones@wwutilities.co.uk
<b>Stakeholder:</b>	Wood
<b>Observation Date:</b>	01-Feb-2018
<b>Observation Time:</b>	15:30
<b>Observation Close Date:</b>	16-Jul-2018
<b>Details of safety observation:</b>	The new mains clamp is not working on the 75 ml main , it does ot work it is not compatible with the 75 ml pipe . The team previously used a strap on clamp and this worked . The new only on works on 63 - 180 not 75 ml
<b>Immediate action taken:</b>	The team raised an Heart Observation and will return the clap to Rod Evans in the stores to pass ontoThomas James to investigaste. They will also pick up another clamp
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No