

Observation Number:	201808470
Originator:	
Date Created:	25-Jun-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Service Line:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Home or Work Related Observation?:	Work
Exact Location or Project of Act/Condition/Safe Behaviour:	Gelli Cottages Cymmer Port Talbot
Observation Type:	Unsafe Condition
Observer Name:	John Royals
Observer Email Address:	steve.edwards@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	18-Jan-2018
Observation Time:	08:15
Observation Close Date:	27-Jun-2018
Details of safety observation:	From approximately the start of the winter time??? The team have been experiencing issues with the stone it's been soaking wet causing puddles whilst whacking the stone trying to make it stick.
Immediate action taken:	The team had to send the stone back yesterday and it was un- useable
Supporting Information:	
Feedback required?:	No