

|   |  |
|---|--|
| <b>Observation Number:</b>  | 201912954  |
| <b>Originator:</b>  |  |
| <b>Date Created:</b>  | 11-Jun-2019  |
| <b>Business Unit:</b>   | Projects   |
| <b>Business Group:</b>  | Process & Chemicals  |
| <b>Project/Office:</b>  | Kemerton Project   |
| <b>Sub Business Group:</b>  | Mining & Minerals  |
| <b>Site/Office Name:</b>  | Kemerton Project Site  |
| <b>Work Related or Non-Work Related Observation?:</b>             | Work Related   |
| <b>Exact Location or Project of Act/Condition/Safe Behaviour:</b> | Security Hut site entrance   |
| <b>Observation Type:</b>  | Unsafe Condition   |
| <b>Observer Name:</b>   | Stephen Andrews  |
| <b>Observer Email Address:</b>                                    | steve.andrews3@woodplc.com   |
| <b>Stakeholder:</b>   | 3rd Party  |
| <b>Observation Date:</b>  | 11-Jun-2019  |
| <b>Observation Time:</b>  | 05:45  |
| <b>Observation Close Date:</b>                                    | 14-Jun-2019  |
| <b>Observation Category:</b>                                      | Work Environment<br>Pedestrian routes (floors, stairs etc.)  |
| <b>Details of safety observation:</b>                             | When waiting for lift from security office to site there is no where to shelter from inclement weather |
| <b>Immediate action taken:</b>                                    |  |
| <b>Supporting Information:</b>                                    |  |
| <b>Feedback required?:</b>  | Yes  |
| <b>Comments from Reviewer</b>                                     |  |
| <b>Closing Comments:</b>  | Sheltered walkways to be provided once permanent car park is installed off site.                       |