

<b>Observation Number:</b>	201809730
<b>Originator:</b>	
<b>Date Created:</b>	11-Jul-2018
<b>Business Unit:</b>	AS EAAA
<b>Business Group:</b>	Operations Services Europe & Africa
<b>Project/Office:</b>	Western Gas Alliance
<b>Service Line:</b>	Transmission & Distribution
<b>Site/Office Name:</b>	Western Gas Alliance 1855005/6
<b>Work Related or Non-Work Related Observation?:</b>	Work Related
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	Heol Yr Forlan
<b>Observation Type:</b>	Unsafe Condition
<b>Observer Name:</b>	Simon Waite
<b>Observer Email Address:</b>	carl.jones@wwutilities.co.uk
<b>Stakeholder:</b>	Contractor
<b>Observation Date:</b>	01-Feb-2018
<b>Observation Time:</b>	11:45
<b>Observation Close Date:</b>	16-Jul-2018
<b>Details of safety observation:</b>	The team were digging down and found a pot ended electric cable not on the plans, they contacted WPD who came to site and found this was a live cable. This has now been dealt with . They also found another cable on site WPD tested and said there was no reading to suggest a live cable
<b>Immediate action taken:</b>	WPD called to site
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No