

Observation Number:	201919502
Originator:	
Date Created:	04-Aug-2019
Business Unit:	Operations
Business Group:	Asia Pacific
Project/Office:	BSP Facilities Rejuvenation Project
Sub Business Group:	APAC Central
Site/Office Name:	BSP Facilities - Offshore
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	DP
Observation Type:	Safe Behaviour
Observer Name:	Imam S
Observer Email Address:	eric.roth@woodplc.com
Stakeholder:	Wood
Observation Date:	04-Aug-2019
Observation Time:	13:00
Observation Close Date:	04-Aug-2019
Observation Category:	Integrity Management Accountability
Name of Individual or Team:	wood crew
Details of safety observation:	observed scaffolding crew working at DP spider deck with correct manual handling technique
Immediate action taken:	keep up the good work.
Supporting Information:	
Feedback required?:	No