

Observation Number:	201810048
Originator:	
Date Created:	16-Jul-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Sub Business Group:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	Tarris Av Kingsteignton
Observation Type:	Unsafe Condition
Observer Name:	Jason Miller
Observer Email Address:	john.dowson@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	09-Feb-2018
Observation Time:	11:00
Observation Close Date:	
Details of safety observation:	Team have staterted to do an RO , Jason Miller is the AE he turned up on site to do a audit and found Electrical Equipment OOD : Conti Board , Extension Leads ,Water Pump
Immediate action taken:	There is a second team so the team will be using their equipment
Supporting Information:	
Feedback required?:	No
Comments from Reviewer	
Cancel Comments:	Not Wood related