

| | |
|---|---|
| Observation Number: | 201808418 |
| Originator: | |
| Date Created: | 24-Jun-2018 |
| Business Unit: | AS EAAA |
| Business Group: | Operations Services Europe & Africa |
| Project/Office: | Western Gas Alliance |
| Sub Business Group: | Transmission & Distribution |
| Site/Office Name: | Western Gas Alliance 1855005/6 |
| Work Related or Non-Work Related Observation?: | Work Related |
| Exact Location or Project of Act/Condition/Safe Behaviour: | East Wales |
| Observation Type: | Unsafe Condition |
| Observer Name: | Richard Date |
| Observer Email Address: | carl.joes@wwutilities.co.uk |
| Stakeholder: | Wood |
| Observation Date: | 08-Jan-2018 |
| Observation Time: | 08:30 |
| Observation Close Date: | 27-Jun-2018 |
| Details of safety observation: | Friday 5th Jan before the team left site the excavation in the rd out number 2 had heras fencing over the excavation all barriered off/ taped safe and secure all signs up for customers to see . Came in this morning and the barriers had been removed from the excavation leaving it open and signs and heras fencing had been removed and thrown everywhere. A customer in number16 came out and told the Team Leader that over the weekend a vehicle hit an arrow sign that had been thrown and she was just informing the T/L incase we have a phone call |
| Immediate action taken: | Team Leader reported on the heart observation log to keep us updated and just in case we have a phone call regarding this . Team tided up the site and made it safe and secure |
| Supporting Information: | |
| Feedback required?: | No |