

| | |
|---|---|
| Originator: | |
| Date Created: | 24-Jul-2018 |
| Business Unit: | AS EAAA |
| Business Group: | Operations Services Europe & Africa |
| Project/Office: | Western Gas Alliance |
| Service Line: | Transmission & Distribution |
| Site/Office Name: | Western Gas Alliance 1855005/6 |
| Home or Work Related Observation?: | Work |
| Exact Location or Project of Act/Condition/Safe Behaviour: | Chestnut Way, Gurnos |
| Observation Type: | Unsafe Condition |
| Observer Name: | Richard Date |
| Observer Email Address: | carl.jones@wwutilities.co.uk |
| Stakeholder: | Wood |
| Observation Date: | 10-Jul-2018 |
| Observation Time: | 13:15 |
| Observation Close Date: | |
| Details of safety observation: | When the team were digging a connection hole , they un covered a cable not on the plans , the cable was in poor condition |
| Immediate action taken: | T/L contact WPD , they have been out to site they though the cable was dead when they split it , the cable was live it was a St Light Column. |
| Supporting Information: | |
| Feedback required?: | No |
| Comments from Reviewer | |
| Cancel Comments: | Near miss cable strike - should've been investigated fully |