

Observation Number:	201808418
Originator:	
Date Created:	24-Jun-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Service Line:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	East Wales
Observation Type:	Unsafe Condition
Observer Name:	Richard Date
Observer Email Address:	carl.joes@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	08-Jan-2018
Observation Time:	08:30
Observation Close Date:	27-Jun-2018
Details of safety observation:	Friday 5th Jan before the team left site the excavation in the rd out number 2 had heras fencing over the excavation all barriered off/ taped safe and secure all signs up for customers to see . Came in this morning and the barriers had been removed from the excavation leaving it open and signs and heras fencing had been removed and thrown everywhere. A customer in number16 came out and told the Team Leader that over the weekend a vehicle hit an arrow sign that had been thrown and she was just informing the T/L incase we have a phone call
Immediate action taken:	Team Leader reported on the heart observation log to keep us updated and just in case we have a phone call regarding this . Team tided up the site and made it safe and secure
Supporting Information:	
Feedback required?:	No