

Observation Number:	201926741
Originator:	
Date Created:	06-Oct-2019
Business Unit:	Specialist Technical Solutions
Business Group:	Mining & Minerals
Project/Office:	Kemerton Project
Service Line:	Australia
Site/Office Name:	Albemarle
Home or Work Related Observation?:	Work
Exact Location or Project of Act/Condition/Safe Behaviour:	SMP tank assembly area
Observation Type:	Safe Condition
Observer Name:	Stephen Andrews
Observer Email Address:	steve.andrews3@woodplc.com
Stakeholder:	Contractor
Observation Date:	03-Oct-2019
Observation Time:	12:45
Observation Close Date:	07-Oct-2019
Observation Category:	Integrity Management Competence
Details of safety observation:	Lifting of roof tank section onto middle section, all procedures followed , lift study in place pre-team talk prior to lift all areas correctly barricaded a task well done.
Immediate action taken:	Congratulated team
Supporting Information:	
Feedback required?:	No