

Observation Number:	201925475
Originator:	
Date Created:	25-Sep-2019
Business Unit:	Specialist Technical Solutions
Business Group:	Mining & Minerals
Project/Office:	Kemerton Project
Service Line:	Australia
Site/Office Name:	Albemarle
Home or Work Related Observation?:	Work
Exact Location or Project of Act/Condition/Safe Behaviour:	WBS 2221 ground slab area
Observation Type:	Unsafe Act
Observer Name:	Simon Ety
Observer Email Address:	simon.etty@woodplc.com
Stakeholder:	Wood
Observation Date:	25-Sep-2019
Observation Time:	13:30
Observation Close Date:	25-Sep-2019
Observation Category:	Contractor Site safety Barrier / Segregation
Details of safety observation:	During an audit it was noticed that flagging had been lowered to allow access to a recently constructed crane pad; this had not been replaced.
Immediate action taken:	Flagging was re-instated
Supporting Information:	
Feedback required?:	No