

| | |
|---|---|
| Originator: | |
| Date Created: | 10-Aug-2016 |
| Business Unit: | AS EAAA |
| Business Group: | Capital Projects EAAA |
| Project/Office: | EPC2 Antwerp |
| Service Line: | SERC |
| Site/Office Name: | EPC2 Antwerp - Site |
| Home or Work Related Observation?: | Work |
| Exact Location or Project of Act/Condition/Safe Behaviour: | Central Control House |
| Observation Type: | Safe Behaviour |
| Observer Name: | Cristian Loi |
| Observer Email Address: | TIOTIE.ExxonmobilAntwerp@fwceu.com |
| Stakeholder: | Contractor |
| Observation Date: | 02-Aug-2016 |
| Observation Time: | 13:00 |
| Observation Close Date: | 12-Aug-2016 |
| Name of Individual or Team: | TECHIMP |
| Details of safety observation: | TECHIMP crew were busy on the migration of emergency push buttons in the central control house from console 6 to console 5. The working area was particular because there inside it's required to pay particular attention to avoid to cause unit trip (the units are in service) and to don't disturb the operators that are working there or leave material on the floor causing trip hazards. In general they perform the activity with good housekeeping and good respect of the work of the other person present in the central control house. |
| Immediate action taken: | No actions but congratulations. |
| Supporting Information: | |
| Feedback required?: | No |