

| | |
|---|---|
| Originator: | |
| Date Created: | 25-Jun-2018 |
| Business Unit: | AS EAAA |
| Business Group: | Operations Services Europe & Africa |
| Project/Office: | Western Gas Alliance |
| Service Line: | Transmission & Distribution |
| Site/Office Name: | Western Gas Alliance 1855005/6 |
| Home or Work Related Observation?: | Work |
| Exact Location or Project of Act/Condition/Safe Behaviour: | 30 Northfield way Swindon |
| Observation Type: | Unsafe Condition |
| Observer Name: | Andy Lock |
| Observer Email Address: | trevor.clark@wwutilities.co.uk |
| Stakeholder: | Wood |
| Observation Date: | 25-Jan-2018 |
| Observation Time: | 08:15 |
| Observation Close Date: | 27-Jun-2018 |
| Details of safety observation: | Complete Utilities:Team arrived on site this morning and found all barriers/ signs were down not sure if it was due to the adverse weather conditions or other vehicles |
| Immediate action taken: | The team picked up all barriers / signs and made the site safe and secure |
| Supporting Information: | |
| Feedback required?: | No |