

<b>Originator:</b>	
<b>Date Created:</b>	12-Jul-2019
<b>Business Unit:</b>	Specialist Technical Solutions
<b>Business Group:</b>	Mining & Minerals
<b>Project/Office:</b>	Kemerton Project
<b>Service Line:</b>	Australia
<b>Site/Office Name:</b>	Albemarle
<b>Home or Work Related Observation?:</b>	Work
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	Access Road into Kemerton site
<b>Observation Type:</b>	Safe Behaviour
<b>Observer Name:</b>	Stephen Andrews
<b>Observer Email Address:</b>	steve.andrews3@woodplc.com
<b>Stakeholder:</b>	Contractor
<b>Observation Date:</b>	08-Jul-2019
<b>Observation Time:</b>	11:15
<b>Observation Close Date:</b>	12-Jul-2019
<b>Observation Category:</b>	Integrity Management Hazard Evaluation & Risk Management
<b>Name of Individual or Team:</b>	Pinjarra Cranes
<b>Details of safety observation:</b>	Accessing and egressing the back of trailer to offload concrete blocks weighing 8T, Hazards were identified and addressed in a professional manner brought to the attention of Wood supervisor and discussed in detail best and safest way forward to complete task successfully
<b>Immediate action taken:</b>	Was impressed that crew did not take it on their own back just to climb onto trailer without thinking they shown due care and attention to the task at hand congratulated on job thought process they put in simple but affective.
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No