

Originator:	
Date Created:	24-Jun-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Service Line:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Home or Work Related Observation?:	Work
Exact Location or Project of Act/Condition/Safe Behaviour:	Bull Walk Rd Chepstow
Observation Type:	Unsafe Condition
Observer Name:	David Rees
Observer Email Address:	trevor.clark@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	09-Jan-2018
Observation Time:	10:00
Observation Close Date:	27-Jun-2018
Details of safety observation:	Intervention team ISL - Reinstatement are working in a private (pathway) this is very tricky going up the steps x 10 with a wheel barrow due to slips / trips
Immediate action taken:	Rang in a heart observation
Supporting Information:	
Feedback required?:	No