

<b>Originator:</b>	
<b>Date Created:</b>	06-Apr-2018
<b>Business Unit:</b>	AS EAAA
<b>Business Group:</b>	Capital Projects EAAA
<b>Project/Office:</b>	SPIN - CONTRAST MEDIA PLANT EXPANSION
<b>Service Line:</b>	SERC
<b>Site/Office Name:</b>	Spin- CMPE Site
<b>Home or Work Related Observation?:</b>	Work
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	accesso edificio SPIN
<b>Observation Type:</b>	Safe Behaviour
<b>Observer Name:</b>	sergi domenico
<b>Observer Email Address:</b>	domenico.sergi@woodplc.com
<b>Stakeholder:</b>	Wood
<b>Observation Date:</b>	06-Apr-2018
<b>Observation Time:</b>	10:00
<b>Observation Close Date:</b>	06-Jun-2018
<b>Name of Individual or Team:</b>	gencantieri
<b>Details of safety observation:</b>	ricordato l'importanza di documentare presenza/assenza in stabilimento sul registro di ingresso. In caso di emergenza il personale di operation ha solo quell mezzo per identificare eventuali persone da soccorrere.
<b>Immediate action taken:</b>	
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No