

Originator:	
Date Created:	09-Jul-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Service Line:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Home or Work Related Observation?:	Work
Exact Location or Project of Act/Condition/Safe Behaviour:	Hamlin Lane Exeter
Observation Type:	Unsafe Act
Observer Name:	Matt Raasch-sotinwa
Observer Email Address:	john.dowson@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	29-Jan-2018
Observation Time:	14:45
Observation Close Date:	
Details of safety observation:	Fittings on site were left discarded within the storage compound in clear bags
Immediate action taken:	Matt spoke to the T/I and told them to clear up the fittings and store in a proper/ correct manner
Supporting Information:	
Feedback required?:	No
Comments from Reviewer	
Cancel Comments:	Not Wood related