

| | |
|---|--|
| Originator: | |
| Date Created: | 10-Aug-2019 |
| Business Unit: | Specialist Technical Solutions |
| Business Group: | Mining & Minerals |
| Project/Office: | Kemerton Project |
| Service Line: | Australia |
| Site/Office Name: | Albemarle |
| Home or Work Related Observation?: | Work |
| Exact Location or Project of Act/Condition/Safe Behaviour: | SMP Stage one office complex |
| Observation Type: | Safe Behaviour |
| Observer Name: | Stephen Andrews |
| Observer Email Address: | steve.andrews3@woodplc.com |
| Stakeholder: | Contractor |
| Observation Date: | 10-Aug-2019 |
| Observation Time: | 07:15 |
| Observation Close Date: | 10-Aug-2019 |
| Observation Category: | Integrity Management Practices and Procedures |
| Name of Individual or Team: | Atco |
| Details of safety observation: | Observed Atco contractors installing office buildings, checked JHA & lift study all was in place and correctly filled out, Tag lines used all body parts away from line of fire good communication between rigger and crane operator , crane foot print fully barricaded off a job well done |
| Immediate action taken: | Congratulated crew on job well done |
| Supporting Information: | |
| Feedback required?: | No |