

<b>Observation Number:</b>	201921469
<b>Originator:</b>	
<b>Date Created:</b>	21-Aug-2019
<b>Business Unit:</b>	TCS
<b>Business Group:</b>	Mining & Minerals
<b>Project/Office:</b>	Kemerton Project
<b>Service Line:</b>	APAC
<b>Site/Office Name:</b>	Kemerton Project Site
<b>Work Related or Non-Work Related Observation?:</b>	Work Related
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	Train One area 2221
<b>Observation Type:</b>	Safe Behaviour
<b>Observer Name:</b>	Stephen Andrews
<b>Observer Email Address:</b>	steve.andrews3@woodplc.com
<b>Stakeholder:</b>	Contractor
<b>Observation Date:</b>	21-Aug-2019
<b>Observation Time:</b>	13:30
<b>Observation Close Date:</b>	21-Aug-2019
<b>Observation Category:</b>	Travel and Safety away from the office Manual Handling
<b>Name of Individual or Team:</b>	Civmec
<b>Details of safety observation:</b>	Observed group laying mesh reinforcing for concrete slab pour, when lifting mesh sheet all four doing the lifting had the correct posture for doing the lift and lifted as a team carried over and laid into position doing the exact reverse .
<b>Immediate action taken:</b>	Told supervisor and group a job well executed
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No