

| | |
|---|--|
| Observation Number: | 201810055 |
| Originator: | |
| Date Created: | 16-Jul-2018 |
| Business Unit: | AS EAAA |
| Business Group: | Operations Services Europe & Africa |
| Project/Office: | Western Gas Alliance |
| Service Line: | Transmission & Distribution |
| Site/Office Name: | Western Gas Alliance 1855005/6 |
| Work Related or Non-Work Related Observation?: | Work Related |
| Exact Location or Project of Act/Condition/Safe Behaviour: | Jct of Chestnut Way and Popular Way, Gurnos |
| Observation Type: | Unsafe Condition |
| Observer Name: | Peter Tyler |
| Observer Email Address: | carl.jones@wwutilities.co.uk |
| Stakeholder: | Wood |
| Observation Date: | 13-Feb-2018 |
| Observation Time: | 14:15 |
| Observation Close Date: | 18-Jul-2018 |
| Details of safety observation: | Weighted ballasts required for barriers on Jct of Chestnut Way and Popular Way, Gurnos |
| Immediate action taken: | Pete Tyler requested from stores. |
| Supporting Information: | |
| Feedback required?: | No |