Originator:	
Date Created:	11-Jan-2019
Business Unit:	AS EAAA
Business Group:	Capital Projects EAAA
Project/Office:	PREEM
Service Line:	NEMEA
Site/Office Name:	Amec FW / VGO Project PREEM
Home or Work Related Observation?:	Work
Exact Location or Project of Act/Condition/Safe Behaviour:	West side Pipe rack top floor.
Observation Type:	Unsafe Condition
Observer Name:	Kolliboina, Vamsi
Observer Email Address:	vamsi.kolliboina@woodplc.com
Stakeholder:	Wood
Observation Date:	11-Jan-2019
Observation Time:	10:30
Observation Close Date:	05-Feb-2019
Observation Category:	Work Environment Pedestrian routes (floors, stairs etc.)
Details of safety observation:	The tarpaulin sheet spread on the top floor of the rack for protection from blasting is not secure in places and is coming off and can be a trip hazard for the workforce walking on it.
Immediate action taken:	
Supporting Information:	
Feedback required?:	No

Reasons for Amendment

Comment	Entered By	Date Entered
Obs name	Paul Harrington	05-April-2019 11:23