

Observation Number:	201914001
Originator:	
Date Created:	25-Jun-2019
Business Unit:	Specialist Technical Solutions
Business Group:	Mining & Minerals
Project/Office:	Kemerton Project
Service Line:	Australia
Site/Office Name:	Albemarle
Home or Work Related Observation?:	Work
Exact Location or Project of Act/Condition/Safe Behaviour:	Contractor Car Park
Observation Type:	Unsafe Condition
Observer Name:	Stephen Andrews
Observer Email Address:	steve.andrews3@woodplc.com
Stakeholder:	Contractor
Observation Date:	26-Jun-2019
Observation Time:	05:15
Observation Close Date:	26-Jun-2019
Observation Category:	Work Environment Traffic routes and parking areas
Details of safety observation:	While driving into site car park observed some large pot holes on the entrance to the car park just as you turn before security .
Immediate action taken:	
Supporting Information:	
Feedback required?:	No