

Observation Number:	201810285
Originator:	
Date Created:	18-Jul-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Service Line:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	Ayron St Ferndale
Observation Type:	Unsafe Condition
Observer Name:	Nathan Quinn
Observer Email Address:	carl.jones@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	29-May-2018
Observation Time:	11:30
Observation Close Date:	12-Sep-2018
Details of safety observation:	Welfare Unit WGAP 13119 :Light in the toilet , flush not working in the Toilet , plate missing from the microwave , kettle covered in limscale . This unit came from Steve Terry moved to Nathan Quinn
Immediate action taken:	These issues were reported to James Spencer this morning and also called into the Heart Observation line . James Spencer passed onto BT , who will be sorting the issues within 48 hours
Supporting Information:	
Feedback required?:	No