

Observation Number:	201905813
Originator:	
Date Created:	27-Mar-2019
Business Unit:	Asset Solutions Americas
Business Group:	Downstream & Chemicals
Project/Office:	US & LATAM - Houston Office (for use prior to April 1)
Service Line:	US & Latin America
Site/Office Name:	US & LATAM - Houston Office
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	Celanese Bishop Facility
Observation Type:	Unsafe Condition
Observer Name:	Ernest Ortega
Observer Email Address:	ernest.ortega_contractor@celanese.com
Stakeholder:	Wood
Observation Date:	27-Mar-2019
Observation Time:	14:00
Observation Close Date:	28-Mar-2019
Observation Category:	Work Environment Pedestrian routes (floors, stairs etc.)
Details of safety observation:	Light rain and the metal stairs and handrails were wet and slippery
Immediate action taken:	Took extra precaution not to slip.
Supporting Information:	
Feedback required?:	No