

Observation Number:	201902049
Originator:	
Date Created:	12-Feb-2019
Business Unit:	TCS
Business Group:	E&I Americas
Project/Office:	EIA United States - West
Service Line:	Americas
Site/Office Name:	Carlsbad Brine Well Remediation
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	Drilling Rig being used onsite
Observation Type:	Unsafe Act
Observer Name:	Matthew Magill
Observer Email Address:	matthew.magill@woodplc.com
Stakeholder:	Wood
Observation Date:	10-Feb-2019
Observation Time:	14:15
Observation Close Date:	12-Feb-2019
Observation Category:	Contractor Site safety Safety awareness & behaviour
Details of safety observation:	3rd party driller's hand climbed onto drill rig to fix hose on drive head. Began to climb up mast to reach the hose on drive head.
Immediate action taken:	Instructed the driller's hand that he cannot climb up things without fall protection/harness or tied off ladder. Driller lowered the drive head to a workable height from the rig floor.
Supporting Information:	
Feedback required?:	No