

Originator:	
Date Created:	24-Jul-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Service Line:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Home or Work Related Observation?:	Work
Exact Location or Project of Act/Condition/Safe Behaviour:	The rear of Rhondda Terrace Ferndale
Observation Type:	Unsafe Condition
Observer Name:	Peter Tyler
Observer Email Address:	carl.jones@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	16-Jul-2018
Observation Time:	08:15
Observation Close Date:	21-Sep-2018
Details of safety observation:	Welfare unit on site WGAP 13119, has not been cleaned for 3 weeks
Immediate action taken:	Contacted A1 Loo hire they will be cleaning the Welfare Unit Tomorrow. Cleaned ref Peter Tyler 19/07/2018
Supporting Information:	
Feedback required?:	No