

Originator:	
Date Created:	16-Jul-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Service Line:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Home or Work Related Observation?:	Work
Exact Location or Project of Act/Condition/Safe Behaviour:	St Lukes Road, Tredegar
Observation Type:	Unsafe Act
Observer Name:	Peter Tyler
Observer Email Address:	carl.jones@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	08-Feb-2018
Observation Time:	08:30
Observation Close Date:	18-Jul-2018
Details of safety observation:	Chapter 8 - 2 road arrows positioned the wrong way around; tipped on their side.
Immediate action taken:	Richard rang stores to send out new arrows.
Supporting Information:	
Feedback required?:	No