

Originator:	
Date Created:	24-Jun-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Service Line:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Home or Work Related Observation?:	Work
Exact Location or Project of Act/Condition/Safe Behaviour:	Beech Rd Weston Super Mare
Observation Type:	Unsafe Condition
Observer Name:	Sacha Ring
Observer Email Address:	trevor.clark@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	04-Jan-2018
Observation Time:	08:15
Observation Close Date:	27-Jun-2018
Details of safety observation:	Sacha turned up on site to do a site visit and found the site unsafe due to high winds.
Immediate action taken:	He immediately made the site safe and secure contacted the reinstatement team to return and tarmac and contacted the barrier man
Supporting Information:	
Feedback required?:	Yes
Comments from Reviewer	
Closing Comments:	Job complete. Correct action was taken when highlighting the weather conditions