

<b>Originator:</b>	
<b>Date Created:</b>	16-Jul-2018
<b>Business Unit:</b>	AS EAAA
<b>Business Group:</b>	Operations Services Europe & Africa
<b>Project/Office:</b>	Western Gas Alliance
<b>Service Line:</b>	Transmission & Distribution
<b>Site/Office Name:</b>	Western Gas Alliance 1855005/6
<b>Home or Work Related Observation?:</b>	Work
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	Melcot Close Kingsteignton
<b>Observation Type:</b>	Unsafe Condition
<b>Observer Name:</b>	Jason Miller
<b>Observer Email Address:</b>	john.dowson@wwutilities.co.uk
<b>Stakeholder:</b>	Wood
<b>Observation Date:</b>	08-Feb-2018
<b>Observation Time:</b>	12:15
<b>Observation Close Date:</b>	
<b>Details of safety observation:</b>	The van in the teams van is in very poor condition , it's a potential trip hazard
<b>Immediate action taken:</b>	JM has spoken to the T/L and he is going to fix the floor of the van with new plywood
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No
<b>Comments from Reviewer</b>	
<b>Cancel Comments:</b>	Not Wood related