

|   |   |
|---|---|
| <b>Originator:</b>  |   |
| <b>Date Created:</b>  | 16-Jul-2018   |
| <b>Business Unit:</b>   | AS EAAA   |
| <b>Business Group:</b>  | Operations Services Europe & Africa   |
| <b>Project/Office:</b>  | Western Gas Alliance  |
| <b>Service Line:</b>  | Transmission & Distribution   |
| <b>Site/Office Name:</b>  | Western Gas Alliance 1855005/6  |
| <b>Home or Work Related Observation?:</b>                         | Work  |
| <b>Exact Location or Project of Act/Condition/Safe Behaviour:</b> | cwmbach rd, fforestfach   |
| <b>Observation Type:</b>  | Safe Behaviour  |
| <b>Observer Name:</b>   | J Ross  |
| <b>Observer Email Address:</b>                                    | trevor.clark@wwutilities.co.uk  |
| <b>Stakeholder:</b>   | Contractor  |
| <b>Observation Date:</b>  | 05-Feb-2018   |
| <b>Observation Time:</b>  | 11:45   |
| <b>Observation Close Date:</b>                                    |   |
| <b>Name of Individual or Team:</b>                                | ISL   |
| <b>Details of safety observation:</b>                             | ISL:interim to perm works. Traffic flow to high and would cause considerable obstructions and congestion. |
| <b>Immediate action taken:</b>                                    | works aborted and replan for a weekend when traffic flow is reduced on this road.                         |
| <b>Supporting Information:</b>                                    |   |
| <b>Feedback required?:</b>  | No  |
| <b>Comments from Reviewer</b>                                     |   |
| <b>Cancel Comments:</b>   | Not wood related  |