

Originator:	
Date Created:	16-Jul-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Service Line:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Home or Work Related Observation?:	Work
Exact Location or Project of Act/Condition/Safe Behaviour:	Melcot Close Kingsteignton
Observation Type:	Unsafe Condition
Observer Name:	Jason Miller
Observer Email Address:	john.dowson@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	08-Feb-2018
Observation Time:	12:15
Observation Close Date:	
Details of safety observation:	The van in the teams van is in very poor condition , it's a potential trip hazard
Immediate action taken:	JM has spoken to the T/L and he is going to fix the floor of the van with new plywood
Supporting Information:	
Feedback required?:	No
Comments from Reviewer	
Cancel Comments:	Not Wood related