

Originator:	
Date Created:	24-Jun-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Service Line:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Home or Work Related Observation?:	Work
Exact Location or Project of Act/Condition/Safe Behaviour:	Gannet Road Western Super Mare
Observation Type:	Unsafe Condition
Observer Name:	Trevor Clark
Observer Email Address:	trevor.clark@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	09-Jan-2018
Observation Time:	11:00
Observation Close Date:	27-Jun-2018
Details of safety observation:	Broken kerb lifter on site needs to be fixed or replaced
Immediate action taken:	Trevor Clark discussed this with the team and they are going to get it fixed or replaced asap
Supporting Information:	
Feedback required?:	No