

Observation Number:	201810247
Originator:	
Date Created:	18-Jul-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Sub Business Group:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	Hardwick Hill, Chepstow
Observation Type:	Unsafe Act
Observer Name:	Phil Teasdale
Observer Email Address:	carl.jones@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	28-Feb-2018
Observation Time:	09:15
Observation Close Date:	27-Jul-2018
Details of safety observation:	Digger broken down on site.
Immediate action taken:	Fitter come out to look at the problem, told Phil that there is rust in the Diesel, caused by rust in diesel cans when filling up the digger.
Supporting Information:	
Feedback required?:	No
Comments from Reviewer	
Action to be taken:	No LSR breach
Supporting Information:	