

Observation Number:	201810270
Originator:	
Date Created:	18-Jul-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Service Line:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	Ystrad Deri Tredegar
Observation Type:	Unsafe Condition
Observer Name:	Richard Date
Observer Email Address:	carl.jones@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	10-Apr-2018
Observation Time:	13:00
Observation Close Date:	12-Sep-2018
Details of safety observation:	Excavation open , gateways into houses you cant plate because excavation too large . The team have barriered off the excavations and explained to the customers to use there front doors not there back doors
Immediate action taken:	Came in this morning and barriers have been moved and customers/ relatives have been climbing over the excavations . Team have now ordered stone to back fill today as this is Urgent
Supporting Information:	
Feedback required?:	No