

Observation Number:	201810268
Originator:	
Date Created:	18-Jul-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Service Line:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	O/S The Old Gas Yard, Llwynypia Rd , Tonypandy
Observation Type:	Unsafe Condition
Observer Name:	Ian Palmer
Observer Email Address:	carl.jones@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	09-Apr-2018
Observation Time:	09:00
Observation Close Date:	13-Aug-2018
Details of safety observation:	180/63 - Purge tee : When we tested the purge tee it was leaking
Immediate action taken:	We cut the top of so no one else could use it at a later date and replace with a new one
Supporting Information:	
Feedback required?:	No