

Originator:	
Date Created:	30-May-2019
Business Unit:	Specialist Technical Solutions
Business Group:	Mining & Minerals
Project/Office:	Kemerton Project
Service Line:	Australia
Site/Office Name:	Albemarle
Home or Work Related Observation?:	Work
Exact Location or Project of Act/Condition/Safe Behaviour:	kemerton Site lot 7 & 8 stage 2
Observation Type:	Safe Behaviour
Observer Name:	Stephen Andrews
Observer Email Address:	steve.andrews3@woodplc.com
Stakeholder:	Contractor
Observation Date:	30-May-2019
Observation Time:	09:15
Observation Close Date:	30-May-2019
Observation Category:	Contractor Site safety Safety planning
Name of Individual or Team:	Kyle C & S drainage
Details of safety observation:	Observed Kyle from C & S drainage installing sub soil drainage on the above lots , JHA in place and covered all aspects of task, barricading & winn rows established , good house keeping and access egress to trenching
Immediate action taken:	Pat on the back for doing a good job.
Supporting Information:	
Feedback required?:	No