

<b>Originator:</b>	
<b>Date Created:</b>	18-Jul-2018
<b>Business Unit:</b>	AS EAAA
<b>Business Group:</b>	Operations Services Europe & Africa
<b>Project/Office:</b>	Western Gas Alliance
<b>Service Line:</b>	Transmission & Distribution
<b>Site/Office Name:</b>	Western Gas Alliance 1855005/6
<b>Home or Work Related Observation?:</b>	Work
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	Park drive crickhowell
<b>Observation Type:</b>	Unsafe Act
<b>Observer Name:</b>	James Osborne
<b>Observer Email Address:</b>	carl.jones@wwutilities.co.uk
<b>Stakeholder:</b>	Wood
<b>Observation Date:</b>	12-Mar-2018
<b>Observation Time:</b>	14:15
<b>Observation Close Date:</b>	18-Jul-2018
<b>Details of safety observation:</b>	Team using a 75 mil / 32 ml top tee when the nipple snapped off the top tee
<b>Immediate action taken:</b>	The team replaced with a new fitting
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No