

<b>Observation Number:</b>	201809246
<b>Originator:</b>	
<b>Date Created:</b>	03-Jul-2018
<b>Business Unit:</b>	AS EAAA
<b>Business Group:</b>	Operations Services Europe & Africa
<b>Project/Office:</b>	Western Gas Alliance
<b>Sub Business Group:</b>	Transmission & Distribution
<b>Site/Office Name:</b>	Western Gas Alliance 1855005/6
<b>Work Related or Non-Work Related Observation?:</b>	Work Related
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	Maindy Rd Cowbridge
<b>Observation Type:</b>	Unsafe Act
<b>Observer Name:</b>	Christopher John
<b>Observer Email Address:</b>	trevor.clark@wwutilities.co.uk
<b>Stakeholder:</b>	Wood
<b>Observation Date:</b>	26-Jan-2018
<b>Observation Time:</b>	13:15
<b>Observation Close Date:</b>	16-Jul-2018
<b>Details of safety observation:</b>	Intervention : Team digging out kerbs leant the pick against the wall then noticed it had fallen on the footpath
<b>Immediate action taken:</b>	The pick was uplifted straight away and put safe within the barrier system
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No