

Observation Number:	201810278
Originator:	
Date Created:	18-Jul-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Service Line:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	Park View , Brynmawr
Observation Type:	Unsafe Condition
Observer Name:	James Osborne
Observer Email Address:	carl.jones@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	03-May-2018
Observation Time:	09:30
Observation Close Date:	12-Sep-2018
Details of safety observation:	New vac ex driver on site . All paper work and risk assessments completed . While operating power boom caught 3/4" gas service which team cut off and made safe . Team subsequently relayed service as part of planned works .
Immediate action taken:	FLM (James Osborne) had a discussion with Vac Ex driver (Chris) regarding dangers of power loom and to pace himself with team . Good feedback and interaction . No further action deemed required and logged for records only
Supporting Information:	
Feedback required?:	No