

Observation Number:	201810600
Originator:	
Date Created:	24-Jul-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Service Line:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	Chestnut Way, Gurnos
Observation Type:	Unsafe Condition
Observer Name:	Richard Date
Observer Email Address:	carl.jones@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	10-Jul-2018
Observation Time:	13:15
Observation Close Date:	
Details of safety observation:	When the team were digging a connection hole , they un covered a cable not on the plans , the cable was in poor condition
Immediate action taken:	T/L contact WPD , they have been out to site they though the cable was dead when they split it , the cable was live it was a St Light Column.
Supporting Information:	
Feedback required?:	No
Comments from Reviewer	
Cancel Comments:	Near miss cable strike - should've been investigated fully