

<b>Originator:</b>	
<b>Date Created:</b>	25-Jun-2018
<b>Business Unit:</b>	AS EAAA
<b>Business Group:</b>	Operations Services Europe & Africa
<b>Project/Office:</b>	Western Gas Alliance
<b>Service Line:</b>	Transmission & Distribution
<b>Site/Office Name:</b>	Western Gas Alliance 1855005/6
<b>Home or Work Related Observation?:</b>	Work
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	Chestnut Way, Gurnos
<b>Observation Type:</b>	Unsafe Condition
<b>Observer Name:</b>	Richard Date
<b>Observer Email Address:</b>	carl.jones@wwutilities.co.uk
<b>Stakeholder:</b>	Wood
<b>Observation Date:</b>	23-Jan-2018
<b>Observation Time:</b>	13:00
<b>Observation Close Date:</b>	27-Jun-2018
<b>Details of safety observation:</b>	Team found asbestos in an excavation
<b>Immediate action taken:</b>	Team have stopped work contacted FLM who will be coming to site with the appropriate asbestos bagging : correct PPE worn,Dust Masks, White overalls, Double gloves etc. . To disposed of correctly. Ref 95 issued and permit to work issued by Sean Maher
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No