

Observation Number:	201921469
Originator:	
Date Created:	21-Aug-2019
Business Unit:	Specialist Technical Solutions
Business Group:	Mining & Minerals
Project/Office:	Kemerton Project
Service Line:	Australia
Site/Office Name:	Albemarle
Home or Work Related Observation?:	Work
Exact Location or Project of Act/Condition/Safe Behaviour:	Train One area 2221
Observation Type:	Safe Behaviour
Observer Name:	Stephen Andrews
Observer Email Address:	steve.andrews3@woodplc.com
Stakeholder:	Contractor
Observation Date:	21-Aug-2019
Observation Time:	13:30
Observation Close Date:	21-Aug-2019
Observation Category:	Travel and Safety away from the office Manual Handling
Name of Individual or Team:	Civmec
Details of safety observation:	Observed group laying mesh reinforcing for concrete slab pour, when lifting mesh sheet all four doing the lifting had the correct posture for doing the lift and lifted as a team carried over and laid into position doing the exact reverse .
Immediate action taken:	Told supervisor and group a job well executed
Supporting Information:	
Feedback required?:	No