

Observation Number:	201923247
Originator:	
Date Created:	04-Sep-2019
Business Unit:	Specialist Technical Solutions
Business Group:	Mining & Minerals
Project/Office:	Kemerton Project
Service Line:	Australia
Site/Office Name:	Albemarle
Home or Work Related Observation?:	Work
Exact Location or Project of Act/Condition/Safe Behaviour:	Kiln laydown Area
Observation Type:	Safe Behaviour
Observer Name:	Stephen Andrews
Observer Email Address:	steve.andrews3@woodplc.com
Stakeholder:	Contractor
Observation Date:	03-Sep-2019
Observation Time:	08:00
Observation Close Date:	04-Sep-2019
Observation Category:	Integrity Management Practices and Procedures
Name of Individual or Team:	Reehys Brower Civmec
Details of safety observation:	Employee was tasked with buffing rust from Kiln riding rings working from EWP, he went about this task diligently making sure all permits and procedures were in place prior to commencing work and after completion called for immediate inspection and permit sign off
Immediate action taken:	Congratulated Reehys on job well done.
Supporting Information:	
Feedback required?:	No