

<b>Observation Number:</b>	201808472
<b>Originator:</b>	
<b>Date Created:</b>	25-Jun-2018
<b>Business Unit:</b>	AS EAAA
<b>Business Group:</b>	Operations Services Europe & Africa
<b>Project/Office:</b>	Western Gas Alliance
<b>Service Line:</b>	Transmission & Distribution
<b>Site/Office Name:</b>	Western Gas Alliance 1855005/6
<b>Work Related or Non-Work Related Observation?:</b>	Work Related
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	Barry Jct Wyndam St
<b>Observation Type:</b>	Safe Behaviour
<b>Observer Name:</b>	John Ross
<b>Observer Email Address:</b>	trevor.clark@wwutilities.co.uk
<b>Stakeholder:</b>	Wood
<b>Observation Date:</b>	23-Jan-2018
<b>Observation Time:</b>	14:15
<b>Observation Close Date:</b>	27-Jun-2018
<b>Name of Individual or Team:</b>	Reinstatement
<b>Details of safety observation:</b>	ISL - Intervention: Team member left a pick on the floor by a team member this was noticed by the T/L straight away
<b>Immediate action taken:</b>	T/L pulled team member to one side and explained danger / trip hazard keeping safe public and team members and told him the site has to remain safe at all times and tools to be put in stored in a correct place when not being used
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No