

Observation Number:	201809252
Originator:	
Date Created:	03-Jul-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Service Line:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	Paganel Road, Minehead
Observation Type:	Unsafe Condition
Observer Name:	Nick Hartley
Observer Email Address:	trevor.clark@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	21-Jan-2018
Observation Time:	14:00
Observation Close Date:	
Details of safety observation:	CJ Lynch : Screw to hold down footboard to footpath had been left sticking out of the bottom of the board. When nick was loading the van to clear site, the screw caught his shirt and ripped it.
Immediate action taken:	Team removed screw from board to prevent anyone else catching it. Claw hammers have been issued for teams to remove any screws from boards.
Supporting Information:	
Feedback required?:	No
Comments from Reviewer	
Cancel Comments:	Not a Wood observation